

# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-L335369-12-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

**Issued to:** ORIENTAL MOTOR CO LTD  
5-8-3 Tokodai TSUKUBA-SHI, IBARAKI-KEN 300-2635  
Japan

**This is to certify that  
representative samples of**

NDMM2 - Incomplete Rotating Machines and Rotating  
Machine Parts - Component

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.


**Standard(s) for Safety:** UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision  
Date: 2020-11-05

**Additional Information:** See the UL Online Certifications Directory at  
<https://iq.ulprospector.com> for additional information

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-L335369-12-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
BLM230-A+	Incomplete Motor Parts
BLM230-A2+	Incomplete Motor Parts
BLM230-AC+	Incomplete Motor Parts
BLM230-AC2+	Incomplete Motor Parts
BLM230-GFV+	Incomplete Motor Parts
BLM230-GFV2+	Incomplete Motor Parts
BLM230HP-ACS+	Incomplete Motor Parts
BLM230HP-AS+	Incomplete Motor Parts
BLM230HP-GFV+	Incomplete Motor Parts
BLM230HPM-ACS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM230HPM-AS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM230HPM-GFV+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM230P-A+	Incomplete Motor Parts
BLM230P-A2+	Incomplete Motor Parts
BLM230P-AC+	Incomplete Motor Parts
BLM230P-AC2+	Incomplete Motor Parts
BLM230P-GFV+	Incomplete Motor Parts
BLM230P-GFV2+	Incomplete Motor Parts
BLM260-A+	Incomplete Motor Parts
BLM260-A2+	Incomplete Motor Parts
BLM260-AC+	Incomplete Motor Parts
BLM260-AC2+	Incomplete Motor Parts
BLM260HP-ACS+	Incomplete Motor Parts
BLM260HP-AS+	Incomplete Motor Parts
BLM260HPM-ACS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM260HPM-AS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM260P-A+	Incomplete Motor Parts
BLM260P-A2+	Incomplete Motor Parts
BLM260P-AC+	Incomplete Motor Parts
BLM260P-AC2+	Incomplete Motor Parts
BLM460S-GFV+	Incomplete Motor Parts
BLM460S-GFV2+	Incomplete Motor Parts
BLM460SHP-GFV+	Incomplete Motor Parts
BLM460SHPK+	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-L335369-12-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

BLM460SHPM-GFV+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM460SP-GFV+	Incomplete Motor Parts
BLM460SP-GFV2+	Incomplete Motor Parts
BLM5120-A+	Incomplete Motor Parts
BLM5120-A2+	Incomplete Motor Parts
BLM5120-AC+	Incomplete Motor Parts
BLM5120-AC2+	Incomplete Motor Parts
BLM5120-GFV+	Incomplete Motor Parts
BLM5120-GFV2+	Incomplete Motor Parts
BLM5120HP-ACS+	Incomplete Motor Parts
BLM5120HP-AS+	Incomplete Motor Parts
BLM5120HP-GFV+	Incomplete Motor Parts
BLM5120HPK+	Incomplete Motor Parts
BLM5120HPM-ACS+	Incomplete Motor Parts
BLM5120HPM-AS+	Incomplete Motor Parts
BLM5120HPM-GFV+	Incomplete Motor Parts
BLM5120P-A+	Incomplete Motor Parts
BLM5120P-A2+	Incomplete Motor Parts
BLM5120P-AC+	Incomplete Motor Parts
BLM5120P-AC2+	Incomplete Motor Parts
BLM5120P-GFV+	Incomplete Motor Parts
BLM5120P-GFV2+	Incomplete Motor Parts
BLM5200-A+	Incomplete Motor Parts
BLM5200-AC+	Incomplete Motor Parts
BLM5200HP-ACS+	Incomplete Motor Parts
BLM5200HP-AS+	Incomplete Motor Parts
BLM5200HPK+	Incomplete Motor Parts
BLM5200HPM-ACS+	Incomplete Motor Parts
BLM5200HPM-AS+	Incomplete Motor Parts
BLM5200P-A+	Incomplete Motor Parts
BLM5200P-AC+	Incomplete Motor Parts
BLM5300-A+	Incomplete Motor Parts
BLM5300-AC+	Incomplete Motor Parts
BLM5300HP-ACS+	Incomplete Motor Parts
BLM5300HP-AS+	Incomplete Motor Parts
BLM5300HPK+	Incomplete Motor Parts
BLM5400-A+	Incomplete Motor Parts
BLM5400-AC+	Incomplete Motor Parts
BLM5400HP-ACS+	Incomplete Motor Parts
BLM5400HP-AS+	Incomplete Motor Parts
BLM5400HPK+	Incomplete Motor Parts
BLM5400P-A+	Incomplete Motor Parts
BLM5400P-AC+	Incomplete Motor Parts
BLM6200S-GFV+	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-L335369-12-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

BLM6200SHP-GFV+	Incomplete Motor Parts
BLM6200SHPM-GFV+	Incomplete Motor Parts
BLM6200SP-GFV+	Incomplete Motor Parts
BLM6300S-GFV+	Incomplete Motor Parts
BLM6300SHP-GFV+	Incomplete Motor Parts
BLM6400S-GFV+	Incomplete Motor Parts
BLM6400SHP-GFV+	Incomplete Motor Parts
BLM6400SP-GFV+	Incomplete Motor Parts
BLM7200HW-GFV+	Incomplete Motor Parts
BLM7300HW-GFV+, + May be followed by a hyphen and any suffix.	Incomplete Motor Parts
BLM7400HW-GFV+, + May be followed by a hyphen and any suffix.	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-L335369-32-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

**Issued to:** ORIENTAL MOTOR CO LTD  
5-8-3 Tokodai TSUKUBA-SHI, IBARAKI-KEN 300-2635  
Japan

**This is to certify that representative samples of** NDMM8 - Incomplete Rotating Machines and Rotating Machine Parts Certified for Canada - Component  
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.


**Standard(s) for Safety:** CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01, Revision Date: 2017-04-01

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-L335369-32-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
BLM230-A+	Incomplete Motor Parts
BLM230-A2+	Incomplete Motor Parts
BLM230-AC+	Incomplete Motor Parts
BLM230-AC2+	Incomplete Motor Parts
BLM230-GFV+	Incomplete Motor Parts
BLM230-GFV2+	Incomplete Motor Parts
BLM230HP-ACS+	Incomplete Motor Parts
BLM230HP-AS+	Incomplete Motor Parts
BLM230HP-GFV+	Incomplete Motor Parts
BLM230HPM-ACS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM230HPM-AS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM230HPM-GFV+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM230P-A+	Incomplete Motor Parts
BLM230P-A2+	Incomplete Motor Parts
BLM230P-AC+	Incomplete Motor Parts
BLM230P-AC2+	Incomplete Motor Parts
BLM230P-GFV+	Incomplete Motor Parts
BLM230P-GFV2+	Incomplete Motor Parts
BLM260-A+	Incomplete Motor Parts
BLM260-A2+	Incomplete Motor Parts
BLM260-AC+	Incomplete Motor Parts
BLM260-AC2+	Incomplete Motor Parts
BLM260HP-ACS+	Incomplete Motor Parts
BLM260HP-AS+	Incomplete Motor Parts
BLM260HPM-ACS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM260HPM-AS+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM260P-A+	Incomplete Motor Parts
BLM260P-A2+	Incomplete Motor Parts
BLM260P-AC+	Incomplete Motor Parts
BLM260P-AC2+	Incomplete Motor Parts
BLM460S-GFV+	Incomplete Motor Parts
BLM460S-GFV2+	Incomplete Motor Parts
BLM460SHP-GFV+	Incomplete Motor Parts
BLM460SHPK+	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-L335369-32-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

BLM460SHPM-GFV+, + May be followed by a hyphen and any suffix	Incomplete Motor Parts
BLM460SP-GFV+	Incomplete Motor Parts
BLM460SP-GFV2+	Incomplete Motor Parts
BLM5120-A+	Incomplete Motor Parts
BLM5120-A2+	Incomplete Motor Parts
BLM5120-AC+	Incomplete Motor Parts
BLM5120-AC2+	Incomplete Motor Parts
BLM5120-GFV+	Incomplete Motor Parts
BLM5120-GFV2+	Incomplete Motor Parts
BLM5120HP-ACS+	Incomplete Motor Parts
BLM5120HP-AS+	Incomplete Motor Parts
BLM5120HP-GFV+	Incomplete Motor Parts
BLM5120HPK+	Incomplete Motor Parts
BLM5120HPM-ACS+	Incomplete Motor Parts
BLM5120HPM-AS+	Incomplete Motor Parts
BLM5120HPM-GFV+	Incomplete Motor Parts
BLM5120P-A+	Incomplete Motor Parts
BLM5120P-A2+	Incomplete Motor Parts
BLM5120P-AC+	Incomplete Motor Parts
BLM5120P-AC2+	Incomplete Motor Parts
BLM5120P-GFV+	Incomplete Motor Parts
BLM5120P-GFV2+	Incomplete Motor Parts
BLM5200-A+	Incomplete Motor Parts
BLM5200-AC+	Incomplete Motor Parts
BLM5200HP-ACS+	Incomplete Motor Parts
BLM5200HP-AS+	Incomplete Motor Parts
BLM5200HPK+	Incomplete Motor Parts
BLM5200HPM-ACS+	Incomplete Motor Parts
BLM5200HPM-AS+	Incomplete Motor Parts
BLM5200P-A+	Incomplete Motor Parts
BLM5200P-AC+	Incomplete Motor Parts
BLM5300-A+	Incomplete Motor Parts
BLM5300-AC+	Incomplete Motor Parts
BLM5300HP-ACS+	Incomplete Motor Parts
BLM5300HP-AS+	Incomplete Motor Parts
BLM5300HPK+	Incomplete Motor Parts
BLM5400-A+	Incomplete Motor Parts
BLM5400-AC+	Incomplete Motor Parts
BLM5400HP-ACS+	Incomplete Motor Parts
BLM5400HP-AS+	Incomplete Motor Parts
BLM5400HPK+	Incomplete Motor Parts
BLM5400P-A+	Incomplete Motor Parts
BLM5400P-AC+	Incomplete Motor Parts
BLM6200S-GFV+	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-L335369-32-02113102-2  
**Report Reference** E335369-20131120  
**Date** 11-Feb-2022

BLM6200SHP-GFV+	Incomplete Motor Parts
BLM6200SHPM-GFV+	Incomplete Motor Parts
BLM6200SP-GFV+	Incomplete Motor Parts
BLM6300S-GFV+	Incomplete Motor Parts
BLM6300SHP-GFV+	Incomplete Motor Parts
BLM6400S-GFV+	Incomplete Motor Parts
BLM6400SHP-GFV+	Incomplete Motor Parts
BLM6400SP-GFV+	Incomplete Motor Parts
BLM7200HW-GFV+	Incomplete Motor Parts
BLM7300HW-GFV+, + May be followed by a hyphen and any suffix.	Incomplete Motor Parts
BLM7400HW-GFV+, + May be followed by a hyphen and any suffix.	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

