

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20191202-E208200  
**Report Reference** E208200-A6001-UL  
**Issue Date** 2019-DECEMBER-02

**Issued to:** ORIENTAL MOTOR CO LTD  
5-8-3 Tokodai  
TSUKUBA-SHI  
IBARAKI-KEN 300-2635 JAPAN

**This certificate confirms that  
representative samples of**

COMPONENT - AUDIO/VIDEO, INFORMATION AND  
COMMUNICATION TECHNOLOGY EQUIPMENT

Brushless Motor Driver-BLH2D15, BLH2D30, BLH2D50  
All models are followed by suffix, -K, -KD or -KR, and may  
be followed by a hyphen and/or any letters and/or any  
numbers

Have been investigated by UL in accordance with the  
component requirements in the Standard(s) indicated on  
this Certificate. UL Recognized components are incomplete  
in certain constructional features or restricted in  
performance capabilities and are intended for installation in  
complete equipment submitted for investigation to UL LLC.


**Standard(s) for Safety:** UL 62368-1 and CSA C22.2 No. 62368-1-14 Audio/video,  
information and communication technology equipment Part  
1: Safety requirements

**Additional Information:** See the UL Online Certifications Directory at  
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only  
the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified  
and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

