

# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-L64197-121-02106002-2  
**Report Reference** E64197-20060120  
**Date** 18-Nov-2022

**Issued to:** ORIENTAL MOTOR CO LTD  
5-8-3 Tokodai TSUKUBA-SHI, IBARAKI-KEN 300-2635  
Japan

**This is to certify that representative samples of** XEWR8 - Thermal-device-protected Motors Certified for Canada - Component  
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

**Standard(s) for Safety:** CSA C22.2 NO. 77-14, 8th Ed., Issue Date: 2014-08-01, Revision Date: 2015-02-01, CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01, Revision Date: 2017-04-01

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

  
Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-L64197-121-02106002-2  
**Report Reference** E64197-20060120  
**Date** 18-Nov-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

<b>Model</b>	<b>Category Description</b>
FPW425A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW425C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW425S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW540A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW540C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW540S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW560A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW560C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW560S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW690A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW690C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW690S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor

*Deborah Jennings-Conner*

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-L64197-101-02106002-2  
**Report Reference** E64197-20060120  
**Date** 18-Nov-2022

**Issued to:** ORIENTAL MOTOR CO LTD  
5-8-3 Tokodai TSUKUBA-SHI, IBARAKI-KEN 300-2635  
Japan

**This is to certify that representative samples of** XEWR2 - Thermal-device-protected Motors - Component  
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.


**Standard(s) for Safety:** UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision Date: 2020-11-05, UL 1004-3, 2nd Ed., Issue Date: 2015-02-27, Revision Date: 2018-01-31

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

  
Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-L64197-101-02106002-2  
**Report Reference** E64197-20060120  
**Date** 18-Nov-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

<b>Model</b>	<b>Category Description</b>
FPW425A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW425C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW425S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW540A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW540C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW540S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW560A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW560C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW560S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW690A2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW690C2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor
FPW690S2-*, * May or may not be followed by a hyphen and/or any letters and/or suffix numbers.	Legacy Motor

*Deborah Jennings-Conner*

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

